


# SOFTY 2 Memory Map



## Notes:

A7 driving the 8154 M/IO pin is inverted hence RAM and I/O are swapped from normal.

The 8154 repeats 8 times because of incomplete address decoding, typically addressed as shown here.